



DETAIL #:
0100-FEC-870-P-CS
AVM System 100
Forevercoat

Tooled Control Joint

AVM System 100 Forevercoat



Notes:

- 1. Excessive movement at the joint may cause the deck coating above the sealant to crease, deform or fail. Additional Periodic inspections and maintenance of these joints may be required.